



## **TECH BULLETIN**

**TECH BULLETIN NUMBER: 0104**

**DATE: September 23, 2003**

**Subject: V1.4 Equalization Mode**

**Models affected: All ME and RD**

Battery Equalization mode would not start from "Charger Standby" mode. Charger must be in Float or Battery Full for EQ to work. V1.8 fixes EQ so that it will now start from Charger Standby, Float or Full Battery. Charger now restarts in previous mode when coming out of Charger Standby instead of going directly to Float mode. Charger timers now do not run in Charger Standby so Absorption, Float and EQ times are now more accurate.

Magnum Energy Inc.  
Tech Service Dept.